

# Ai10 RECOMMENDED SPARE PARTS LIST

High-speed Direct Drive Machine



## DAMAGEABLE PARTS LIST 易损件清单

No. 序号	Parts No. 代码	English Description 英文描述	Chinese Description 中文描述
1	10117025	Needle	机针DB×1 9#
2	11217001	Needle	机针DB×1 11#
3	11402034	Needle bar	针杆(DLC处理)
4	116015009	Needle plate	2.0针板(E16)
5	116015010	Needle plate	2.0针板(E18)
6	11501600500	Presser foot	活压脚组件
7	116014004	Feed dog(21)	送料牙(21齿)
8	116014003	Feed dog	送料牙(18齿)
9	116018006	Hook asm (Hirose)	广濑旋梭(无油护针)
10	10118003	Bobbin	梭芯
11	11218504	Bobbin case asm.	梭壳
12	10112016	Finger postioner	旋梭定位钩
13	116027005	Thread take-up spring	挑线簧
14	11603102300	Thread tension asm.	底线夹线器
15	11419001	Knife	割线刀
16	11603100100	Bobbin winder unit	绕线器组件
17	104S11006	Screw SM1/8"x44 L=4.5	支针螺钉(进口)SM1/8"x44 L=4.5
18	1160NS15002	Screw SM11/64"x40 L=6.5	针板螺钉SM11/64"x40 L=6.5
19	101S11009	Screw SM9/64"x40 L=10.5	压脚螺钉 SM9/64"x40 L=10.5
20	101S15007	Screw SM1/4"x40 L=8	压杆导架螺钉 SM1/4"x40 L=8
21	116013013	Tread guide for knife	分线片
22	11601900600	/	防鸟巢刀架组件
23	116019001	Moving knife	活动刀(防鸟巢刀架组件的散件)
24	116019002	Auxiliary moving knife	辅助动刀(防鸟巢刀架组件的散件)
25	116019011	Fixing knife	定刀(防鸟巢刀架组件的散件)
26	116012024	/	压线片